CITY GOVERNMENT OF ZAMBOANGA

Bids and Awards Committee Villalobos St., Zamboanga City

SF-GOOD-60

Purchase Request No.: 100-20-07-1513/July 20,2020

Office of the: CGSO-CMO

Amount: **P157,970.00**

REQUEST FOR QUOTATION (53.9 "Small Value Procurement")

Teody Auto Repair Shop RJN Auto Repair Zamboanga Motors

> Date: September 10, 2020 Quotation No.: 0469

Place of Delivery: City General Services Office

Please quote your lowest price on the items listed below, subject to the General Conditions on the Philippine Bidding Documents on Goods, stating the shortest time of delivery and submit your quotation duly signed by your representative on or before September 23, 2020 at 10:00 a.m.

ERWIN E. BERNARDO

BAC-Chairperson

Note: ALL ENTRIES MUST BE TYPEWRITTEN / LEGIBLY WRITTEN.

- 1. DELIVERY PERIOD TEN (10) CALENDAR DAYS
- 2. WARRANTY SHALL BE FOR A PERIOD OF THREE (3) MONTHS FOR EXPENDABLE SUPPLIES, ONE (1) YEAR FOR NON-EXPENDABLE SUPPLIES, FROM DATE OF ACCEPTANCE BY THE PROCURING ENTITY.
- 3. PRICE VALIDITY SHALL BE FOR A PERIOD OF THIRTY (30) CALENDAR DAYS.
- 4. G-EPS REGISTRATION CERTIFICATE SHALL BE ATTACHED UPON SUBMISSION OF THE QUOTATION, IF AVAILABLE.
- 5. BIDDERS SHALL SUBMIT ORIGINAL BROCHURES SHOWING CERTIFICATIONS OF THE PRODUCT BEING OFFERED.
- 6. INDICATE BRAND NAME OF ITEMS BEING OFFERED.
- 7. DROP YOUR QUOTATION IN A SEALED ENVELOPE AND PROPERLY LABELED-
- 8. Bidders are requested to submit PHILGEPS Platinum Certificate, Omnibus Sworn Statement and BUSINESS/MAYOR'S PERMIT
- 9. Downloaded Form must be duly signed by BAC Chairman prior to submission for the opening of bidding documents.
- 10. For Tires and Batteries, ONE (1) YEAR WARRANTY

1. MITSUBISHI L-300 SIE-991 Property No. 19283 Repair brake system, repair aircon, repair wheel bearing front L/R Brake pad L/R 1set, brake shoes 1set, grease ½ liter, brake fluid lliter, condenser 1pc, condenser blower 2pcs, Freon 2kilos, oil Freon ½ liter, inner bearing 2 pcs and outer bearing 2pcs Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SIE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00 Purpose: For official use in the Office of the City Mayor, this city.	ITEM NO.	ITEM & DESCRIPTION	BRAND NAME	QTY	Unit	UNIT PRICE	TOTAL
Repair brake system, repair aircon, repair wheel bearing front L/R Brake pad L/R 1set, brake shoes 1set, grease ½ liter, brake fluid 1liter, condenser 1pc, condenser blower 2pcs, Freon 2kilos, oil Freon ½ liter, inner bearing 2 pcs and outer bearing 2pcs Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40° 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00		JOB ORDER FOR LABOR AND MATERIALS					
front L/R Brake pad L/R 1set, brake shoes 1set, grease ½ liter, brake fluid 1liter, condenser 1pc, condenser blower 2pcs, Freon 2kilos, oil Freon ½ liter, inner bearing 2 pcs and outer bearing 2pcs Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40° 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00	1.			1	unit		
Brake pad L/R 1set, brake shoes 1set, grease ½ liter, brake fluid 1liter, condenser 1pc, condenser blower 2pcs, Freon 2kilos, oil Freon ½ liter, inner bearing 2 pcs and outer bearing 2pcs Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
brake fluid 1 liter, condenser 1 pc, condenser blower 2 pcs, Freon 2 kilos, oil Freon ½ liter, inner bearing 2 pcs and outer bearing 2 pcs Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2 pcs, signal light L/R 2 pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1 set, Tie rod end inner L/R 1 set, brake pad L/R 1 set, brake shoes L/R 1 set, clutch cover 1 pc, clutch lining 1 pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6 liters, wiper blade 2 pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
2pcs, Freon 2kilos, oil Freon ½ liter, inner bearing 2 pcs and outer bearing 2pcs Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
and outer bearing 2pcs Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
Estimated Cost: P38,820.00 2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
2. MITSUBISHI L-300 SEM-240 Property no.12060 Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
Body painting, repair body damage portion, under chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00	2.	/		1	unit		
chassis repair, repair electrical wiring and upholstery Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00				1	unit		
Stoplight L/R 2pcs, signal light L/R 2pcs, bumper light L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
L/R 2 pcs, Tie rod end outer L/R 1set, Tie rod end inner L/R 1set, brake pad L/R 1set, brake shoes L/R 1set, clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
clutch cover 1pc, clutch lining 1pc. Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
Estimated Cost: P97,000.00 3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00		L/R 1set, brake pad L/R 1set, brake shoes L/R 1set,					
3. MITSUBISHI L-300 SJE-991 Property no. 19283 Change oil, change oil filter, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
Change oil, change wiper blade, check electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
electrical wiring, signal light, stoplight Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00	3.			1	unit		
Oil 40" 6liters, wiper blade 2pcs, oil filter and compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
compressor belt tighter (tighten) 1 pc. Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
Estimated Cost: P5,600.00 4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
4. MITSUBISHI L-300 SGD-279 Property no. 13970 Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00							
Change oil, change oil filter, remove radiator and overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00	4	,		1	it	1	
overhaul, repair aircon and change condenser blower Estimated Cost: P16,550.00	7.			1	uiiit		
Estimated Cost: P16,550.00							
	Purpose:	,				I	

Brand ar	nd Model							
Warrant	y	: -						
Price Va	lidity	: _						
After having carefully read and accepted your General Conditions, I/We quote you on the item at prices noted above. ———————————————————————————————————								

Tel. No. / Cellphone No. e-mail address

Date